




Before and After Images





Ground Floor Plan





Roof



Before Conservation



After Conservation



Roof



During Implementation



After Rehabilitation



Minaret



Before Conservation



During Conservation



After Conservation



Dome



Before Conservation



During Conservation



After Conservation




Street facade



Before Conservation



During Conservation



After Conservation



"Qibla



Before Conservation



After Conservation



"Qibla



Before Conservation



After Conservation



"Qibla



Before Conservation



During Conservation



After Conservation



"Qibla




Before Conservation



After Conservation



"Minbar





MARIDANI MOSQUE RESTORATION, Cairo, Egypt

Mashrabiyya Wall



Before Conservation



After Conservation